

CASE STUDY

Schedule of Condition (on behalf of Tenant)

Property:

Multi floor offices

Location:

Town Centre, Maidstone, Kent.
Town Centre, Romford, Essex.

Client:

New Leaseholder

Service Provided:

Schedule of Condition



Summary:

Alexander Harris undertook a detailed schedule of condition of the first, second and third floors of this 1980's concrete frame office building for the ingoing tenant in order to limit their future dilapidations liability prior to entering into a new Lease.

Some of the accommodation was found to be in a poor condition requiring a careful and methodical approach to ensure all areas of disrepair were identified and documented.

For more information contact:

01622 232 595

enquiries@ahpbc.co.uk

